File: ULC Subject C305 ULC-G5.2

April 01, 2011

## **CERTIFICATION BULLETIN 2011-08**

## Withdrawal of ULC/ORD-C305-72, Panic Hardware

TO: Members of the Advisory Council of Underwriters Laboratories of Canada

Others Interested

The requirements for Panic Hardware have been significantly revised and are now contained in CAN/ULC-S132-07, Standard for Emergency Exit and Emergency Fire Exit Hardware.

Effective April 08, 2011, ULC/ORD-C305-72 is withdrawn.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal, Regional Quality Manager & ULC Mark Program Owner, 416-757-3611 ext. 61217 or Gunsimarbir.Paintal@ca.ul.com.

UNDERWRITERS LABORATORIES OF CANADA

Gunsimar Paintal,

Regional Quality Manager & ULC Mark Program Owner