

Corporate Headquarters

7 Underwriters Road Toronto, ON M1R 3B4 Canada www.ulc.ca

tel: 1 416 757 3611 fax: 1 416 757 8915

An affiliate of Underwriters Laboratories Inc.

File: ULC Subject C924

ULC G5.2

March 13, 2009

CERTIFICATION BULLETIN 2009-05

To: Members of the Advisory Council of the Underwriters Laboratories of Canada Others Interested

SUBJECT: First Draft, Proposed Second Edition, ULC/ORD-C924-2009, <u>Photoluminescent and Self-Luminous Exit Signs and Path Markers</u>

Dear Members:

Attached is a copy of the First Draft, Proposed Second Edition, ULC/ORD-C924-2009, *Photoluminescent and Self-Luminous Exit Signs and Path Markers*, for your review and comment.

This Second Edition of this Other Recognized Document (ORD) is intended to be the basis for standard ULC S572. ULC/ORD-C924-2009 outlines requirements for photoluminescent and self-luminous exit signs and path marking systems for use in ordinary locations. Such equipment is intended to provide exit and directional information to assist occupants to rapidly evacuate a facility in the event of a fire alarm, failure of the normal supply or in the event of accident to elements of a system intended to supply, distribute, and control power and illumination essential to safety of human life. These signs and path markers may function as elements of a more extensive wayfinding or wayguidance system.

Please return your ballot and any comments you may have prior to April 13, 2009.

Ballots and comments are to be completed by the Advisory Council members and submitted by e-mail to: Graham.r.Dulmage@ca.ul.com

UNDERWRITERS LABORATORIES OF CANADA

Gunsimar Paintal

Regional Quality Manager & ULC Mark Program Owner

