



Date : 5 juin 2009

ULC-S533-08

BULLETIN D'ACCRÉDITATION N° 2009-11

Destinataires : Clients répertoriés de ULC de FUPLC, de FUPPC, de FULAC, de FUQHC et autres parties intéressées

Objet : Third Edition of the Egress Door Securing and Releasing Devices
CAN/ULC-S533-08

Le présent bulletin fait suite au Bulletin sur les normes ULC 2008-11 annonçant la publication de la troisième édition de la norme CAN/ULC-S533-08, intitulée Dispositifs de fixation et de déblocage de porte de sortie.

Les Laboratoires des assureurs du Canada ont adopté les dispositions de la troisième édition de la norme, et toutes les nouvelles demandes sont vérifiées conformément à ces exigences.

La troisième édition comporte de nouvelles exigences techniques et des exigences révisées. Les modifications apportées à la norme auront une incidence sur les produits actuellement inscrits, une revue des dossiers industriels sera entreprise afin d'assurer la conformité des produits avec les nouvelles exigences et les exigences révisées. Un résumé des exigences de cette édition est joint à titre de référence.

La date d'entrée en vigueur des nouvelles exigences et des exigences révisées de la troisième édition de la norme CAN/ULC-S533-08 a été fixée au 21 avril 2010. À partir de cette date, les produits actuellement inscrits devront être conformes à ces exigences.

Si vous avez des questions portant sur le sujet abordé ci-dessus, veuillez communiquer avec M. Gunsimar Paintal, gestionnaire régional de la qualité et responsable du programme de marque ULC, par téléphone au numéro 416 757-3611, poste 61217.

LABORATOIRES DES ASSUREURS DU CANADA

Gunsimar Paintal,
Gestionnaire régional de la qualité et responsable du programme de marque ULC

" Ce document est signé sur la compréhension que cette traduction est fidèle au contexte de la version anglaise."

SUMMARY OF REQUIREMENTS

The following is a brief summary of the revised paragraphs in the Standard for Egress Door Securing And Releasing Devices, ULC CAN-ULC-S533-08, which have a future Effective Date of April 21, 2010 and the action that may be required to determine compliance.

Paragraphs/Sections	General Subject and Comment
Sec. 1 1.2, 1.4	Scope has rearrangement of terminology. No action required here.
Sec. 2	A new Glossary of terms and rephrasing of terminologies has been included here. No action required here.
3.3	Rearrangement of terminology. No action required here.
4.3	Rearrangement of terminology. No action required here.
5.1.1	Re-alignment of section and figure numbers. No action required here.
5.1.2	Reinforce of current statement with reference to figures and sections in current standard as well as rearrangement of terminologies. No action required here.
5.1.3	Rearrangement of terminology. No action required here.
5.1.4	Reinforce of current statement with reference to figures and sections in current standard as well as rearrangement of terminologies. No action required here.
5.1.5	Rearrangement of terminology. No action required here.
5.2	Re-alignment of section. No action required here.
5.3.2	Rearrangement of terminology. No action required here.
5.3.3	Reinforce of current statement with reference to sections in current standard as well as rearrangement of terminologies. No action required here.
5.4.2	Rearrangement of terminology. No action required here.
5.5	Rearrangement of terminology. No action required here.
5.6	Rearrangement of terminology. No action required here.
6	Rearrangement of terminology and relaxation to allow trade mark used to replace name. No action required here unless manufacturer request to revise marking.
7.2	Re-alignment of figure numbers. No action required here.
7.6	Re-alignment of section numbers. No action required here.
7.7	Re-alignment of section and figure numbers as well as relaxation of requirement being deleted in the consideration it is being covered in previous clause of the same section. No action required here.

Paragraphs/Sections	General Subject and Comment
7.8	Rearrangement of terminology and align with other ULC standard of the same test. No action required here.
7.9.1.2	Re-alignment of section numbers. No action required here.
7.10	Re-alignment of section and figure numbers. No action required here.
7.13	Rearrangement of terminology. No action required here.
7.14	Rearrangement of terminology and align with other ULC standard of the same test. No action required here.
7.15	Condition had been changed, new requirement of 4 hours instead 30 minutes of Vibration had been introduced here that requires testing. Engineering and Testing required.
7.16	Condition had been changed, new requirement for strain relief means provided for flexible cords had been introduced here that requires testing. Engineering and Testing required.
7.17.4	Condition had been changed, new requirement for Salt Spray test for Outdoor / Exterior Door had been introduced here that requires testing. Engineering and Testing required.
7.18	Rearrangement of terminology and align with other ULC standard of the same test. No action required here.
7.19	Rearrangement of terminology. No action required here.
7.20	Condition had been changed, new requirement for Polarity Reversal for device intended to be connected to a specific polarity had been introduced here that requires testing. Engineering and Testing required.
7.21	Condition had been changed, new requirement for Electric Shock Current test for devices has circuit that pertains open circuit voltage larger than 42.4V peak had been introduced here that requires testing. Engineering and Testing required.
7.22	Rearrangement of terminology. No action required here.
7.23	Rearrangement of terminology and align with other ULC standard of the same test. No action required here.
7.24	New requirement. Engineering and Testing required.
7.25	Rearrangement of terminology. No action required here.
7.26	New requirement. Engineering is required.