



File: ULC C252
ULC-G.5.2

July 1st 2019

CERTIFICATION BULLETIN 2019-04

Reinstatement of ULC/ORD-C252, Guide for the Investigation of Gas Pressure Regulators

To: Members of the Advisory Council of Underwriters Laboratories of Canada & Others Interested

This is in continuation to Bulletin 2011-07 wherein a decision was made to withdraw ULC/ORD-C252-75. Subsequent to the release of the April 1st 2011 bulletin, ULC, through the reaffirmation balloting process, have reinstated ULC/ORD-C252-75 (R2018), Guide for the Investigation of Gas Pressure Regulators.

In consideration of input received from the Regulatory Authorities and product manufacturers, ULC initiated an action on April 28th 2018 to have the subject ORD reinstated on an interim basis while awaiting the development and publication of a new Standard. The reinstatement of the ORD was approved by IGAC on August 28th, 2018. This bulletin, therefore, formalizes the reinstatement of ULC/ORD-C252-75 (R2018).

This Certification Bulletin may be forwarded to others who may have an interest in this document.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal at +416.288.2217 or by email at: Gunsimar.Paintal@ul.com.

Sincerely,

Underwriters Laboratories of Canada Inc.

A handwritten signature in black ink, appearing to read 'G. Paintal', is written over a horizontal line.

Gunsimar Paintal
Regional Manager - Accreditations & Compliance
ULC Mark Program Owner