

File: ULC Subject ULC/ORD-C1091-74

July 18, 2025

## **CERTIFICATION BULLETIN 2025-02**

---

### **ULC/ORD-C1091-74, Preliminary Standard for Butterfly Valves for Fire Protection Service has been superseded by ANSI/CAN/UL/ULC-1091:2022**

---

**TO: Members of the Advisory Council of Underwriters Laboratories of Canada**

Subscribers to ULC's Certification Service for-  
HLXS7 - Butterfly Valves Certified for Canada  
Others Interested

---

The requirements for ULC/ORD-C1091-74, Preliminary Standard for Butterfly Valves for Fire Protection Service have now been included in ANSI/CAN/UL/ULC-1091:2022 Standard for Butterfly Valves for Fire Protection Services.

Since the requirements are contained in the above referenced Standard, effective immediately, ULC/ORD-C1091 stands superseded.

ULC will continue to provide Testing and Certification services to the new Standard ANSI/CAN/UL/ULC-1091:2022.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal, at 416-288-2217 or via email at [Gunsimar.Paintal@ul.com](mailto:Gunsimar.Paintal@ul.com).

Sincerely,

**Underwriters Laboratories of Canada Inc.**



**Gunsimar Paintal**

ULC Mark & Program Owner

Regional Manager – Accreditations & Compliance