



File: ULC Subject C525  
ULC-G5.2

April 01, 2011

---

## CERTIFICATION BULLETIN 2011-10

---

### Withdrawal of ULC/ORD-C525-75, Guide for the Investigation of Flame Arresters for Use on Vents of Storage Tanks for Petroleum Oil and Gasoline

---

TO: Members of the Advisory Council of Underwriters Laboratories of Canada  
Others Interested

---

Underwriters Laboratories of Canada has reviewed the subject ORD (Other Recognized Document) and has decided to withdraw this document with no replacement.

Effective April 08, 2011, ULC/ORD-C525-75 is withdrawn.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal, Regional Quality Manager & ULC Mark Program Owner, 416-757-3611 ext. 61217 or [Gunsimarbir.Paintal@ca.ul.com](mailto:Gunsimarbir.Paintal@ca.ul.com).

UNDERWRITERS LABORATORIES OF CANADA

Gunsimar Paintal,  
Regional Quality Manager & ULC Mark Program Owner