



File: ULC Subject C668
ULC-G.5.2

28 January 2016

CERTIFICATION BULLETIN CCH-2016-045

To: Subscribers/Listees to ULC's Listing Service for HOSE VALVES (VTSRC)

Subject: Harmonization of HOSE VALVES (VTSRC) with HOSE VALVES Certified for Canada (VTSR7)

UL as an enterprise is striving to offer to its customers combined Canadian Certification Directories. In doing so, Underwriters Laboratories of Canada Inc. (ULC) and UL LLC are harmonizing their Canadian Certification categories in order to come up with a single Canadian Listing Directory for certified (Listed) products.

Consequently, UL is harmonizing the certification category HOSE VALVES (VTSRC) with the certification category HOSE VALVES Certified for Canada (VTSR7). As the category VTSRC is being harmonized, the Product Listings that are currently certified under VTSRC will now be under VTSR7.

The harmonized categories will represent manufacturers who received authorization from ULC and UL LLC to use their respective marks for Canada.

There are certain administrative activities that are taking place; one such activity is harmonizing the Category Control Numbers (CCN's, an internal terminology used for tracking) resulting in a combined Canadian Listing Directory. Any necessary revisions to your File will be notified and will be at no charge to you. We anticipate completing this transition by March 31, 2016.

Your Field Representative can assist you with any questions regarding the change in category. If you have additional questions please contact Monica Westphal via phone at (847)-664-1228, or email Monica.Westphal@ul.com.

Please share this Bulletin with other interested parties within your organization.

Sincerely,

**Issued under the joint responsibility of Underwriters Laboratories of Canada Inc. & UL LLC.
This Bulletin has been reviewed and approved by:**

Monica Westphal
Engineering Leader
BLST, Fire Suppression

Jeff Hebenstreit
Principal Engineer
BLST, Fire Suppression

A handwritten signature in black ink, appearing to read 'G. Paintal', with a horizontal line underneath.

Gunsimar Paintal
Regional Manager - Accreditation & Quality
ULC Mark Program Owner