



File: ULC C263.1, ULC-G.5.2

January 25, 2018

CERTIFICATION BULLETIN 2018-05

Withdrawal of ORD and Certification program for ULC/ORD-C263.1-99, Sprinkler-Protected Window Systems

TO: Members of the Advisory Council of Underwriters Laboratories of Canada
Others Interested

Underwriters Laboratories of Canada has reviewed the subject ORD (Other Recognized Document) and has decided to withdraw this document with no replacement.

Effective January 16, 2018, ULC has discontinued the Testing & Certification to ULC/ORD-C263.1-99, Sprinkler-Protected Window Systems and the ORD is withdrawn.

ULC reviews its certification programs on an ongoing basis and the decision to exit was driven by business needs.

ULC Standards will continue to work with stakeholders to facilitate the development of consensus based standards. Should the stakeholders be interested in proposing standards development in this area, a New Work Item Proposal would need to be submitted to ULC Standards.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal, at 416-288-2217 or Gunsimar.Paintal@ul.com.

Sincerely,

Underwriters Laboratories of Canada Inc.

Gunsimar Paintal
Regional Manager – Accreditations & Quality
ULC Mark Program Owner