



CERTIFICATION BULLETIN 2018-15

Reinstatement of ULC/ORD-C263.1-99, Sprinkler-Protected Window Systems

To: Members of the Advisory Council of Underwriters Laboratories of Canada & Others Interested

This is in continuation to Bulletin 2018-05 wherein a decision was made to withdraw the ORD ULC/ORD-C263.1-99. Subsequent to the release of the January 25, 2018 bulletin, ULC has initiated an effort to develop a new standard for window sprinklers, CAN/ULC-S136, Standard Method of Fire Test of Sprinkler-Protected Window Systems. The development/publication of this Standard was assigned a high priority, however, there has been an unforeseen delay.

In consideration of input received from the fire protection community including those involved in enforcement, ULC initiated action to have the subject ORD reinstated on an interim basis while awaiting the development and publication of the new Standard. The reinstatement of the ORD was approved by CCFMFC on Dec 15, 2018. Therefore, effective immediately, ULC is pleased to confirm the reinstatement of the ORD ULC/ORD-C263.1-99(R2018).

This ORD can be ordered for \$160.00 CAD (PDF) or \$200.00 CAD (Hardcopy) from the ULC Standards website at www.ulc.ca. The process can be initiated by clicking on "Purchase ULC Standards Material".

This Certification Bulletin may be forwarded to others who may have an interest in this document.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal at +416.288.2217 or by email at: Gunsimar.Paintal@ul.com.

Sincerely,

Underwriters Laboratories of Canada Inc.

Gunsimar Paintal
Regional Manager - Accreditations & Quality
ULC Mark Program Owner