



File: ULC S532, ULC-G.5.2

April 20, 2020

CERTIFICATION BULLETIN 2020-03

CERTIFICATION PROGRAM FOR FIRE EXTINGUISHER SERVICE AGENCIES – CHANGES TO INSPECTION FREQUENCY

To: Members of the Advisory Council of Underwriters Laboratories of Canada
Subscribers to ULC's Certification Service for:
GLOQC - Fire Extinguisher Service Agencies

Underwriters Laboratories of Canada Inc. (ULC) is continually reviewing its programs with an aim to better align with industry practice. Effective immediately, the inspection frequencies for Fire Extinguisher Service Agencies (GLOQC) have been revised from 4 (four) inspections per year to 2 (two) inspections per year.

Your assigned Field Inspector will be able to assist you with any clarifications during the next scheduled inspection.

Any questions concerning this bulletin should be directed to Mr. Gunsimar Paintal, at 416-288-2217 or via email to Gunsimar.Paintal@ul.com.

Sincerely,

Underwriters Laboratories of Canada Inc.

Gunsimar Paintal
ULC Mark & Program Owner
Regional Manager – Accreditations & Compliance