



File: ULC Subject ULC-S529  
ULC/ORD-C529, ULC-S530, ULLC-S525  
ULC-G.5.2

January 7, 2022

## CERTIFICATION BULLETIN CCH-2022-273

---

**To: Subscribers/Listees to ULC's Listing Service for [Fire and Alarm Equipment] (Detectors, Automatic) Smoke Detectors for Fire Alarm Systems (UROXC)**

---

**Subject: Harmonization of [Fire and Alarm Equipment] (Detectors, Automatic) Smoke Detectors for Fire Alarm Systems (UROXC) with [Signal and Fire Alarm Equipment and Services] (Detectors, Automatic Fire) Smoke Detectors for Fire Alarm Systems Certified for Canada (UROX7)**

---

UL as an enterprise is striving to offer to its customers combined Canadian Certification Directories. Continuing with the effort, Underwriters Laboratories of Canada Inc. (ULC) and UL LLC are harmonizing their Canadian Certification categories in order to come up with a single Canadian Listing Directory for certified (Listed) products.

Consequently, UL is harmonizing the certification category [Fire and Alarm Equipment] (Detectors, Automatic) Smoke Detectors for Fire Alarm Systems (UROXC) with the certification category [Signal and Fire Alarm Equipment and Services] (Detectors, Automatic Fire) Smoke Detectors for Fire Alarm Systems Certified for Canada (UROX7). As the category UROXC is being harmonized, the Product Listings and/or designs that are currently certified under UROXC will now be under UROX7.

The harmonized categories will represent manufacturers who received authorization from ULC and UL LLC to use their respective marks for Canada.

There are certain administrative activities that are taking place; one such activity is harmonizing the Category Control Numbers (CCN's, an internal terminology used for tracking) resulting in a combined Canadian Listing Directory. Any necessary revisions to your File will be notified and will be at no charge to you. We anticipate completing this transition by Jan 31, 2022.

Your Field Representative can assist you with any questions regarding the change in category. If you have additional questions please contact William Hoffman via phone at 1(847)664-3976, or email William.T.Hoffman@ul.com.

Please share this Bulletin with other interested parties within your organization.

Sincerely,

**Issued under the joint responsibility of Underwriters Laboratories of Canada Inc. & UL LLC.  
This Bulletin has been reviewed and approved by:**

**William Hoffman**  
Engineering Manager / Leader  
TIC, BE

**David Mills**  
Principal Engineer  
TIC, BE

**Gunsimar Paintal**  
Regional Manager - Accreditations & Compliance  
ULC Mark Program Owner