

May 4, 2023

CERTIFICATION BULLETIN 2023-02

ULC/ORD-C1254.18, Servicing of Restaurant Cooking Area Extinguishing Systems has been superseded by CAN/ULC-S594: 2021

TO: Members of the Advisory Council of Underwriters Laboratories of Canada

Subscribers to ULC's Certification Service for-
GLXXC - Restaurant Cooking Area Fire Extinguishing Systems Servicing Agents
Others Interested

The requirements in ULC/ORD-C1254.18, Servicing of Restaurant Cooking Area Extinguishing Systems have been included in CAN/ULC-S594:2021, Standard for the Servicing of Commercial Cooking Area Extinguishing Systems.

Since the requirements are contained in the above reference standard, effective immediately, ULC/ORD-C1254.18 stands superseded.

ULC will continue to provide Testing and Certification services to the new Standard CAN/ULC-S594: 2021.

Any questions concerning the above should be directed to Mr. Gunsimar Paintal, at 416-288-2217 or via email at Gunsimar.Paintal@ul.com.

Sincerely,

Underwriters Laboratories of Canada Inc.



Gunsimar Paintal

ULC Mark & Program Owner

Regional Manager – Accreditations & Compliance